

ECS/EMD Configuration Change Request

Page 1 of

Page(s)

1. Originator Maryellen Corbett	2. Log Date: 02/11/04	3. CCR #: 04-0098	4. Rev: —	5. Tel: 301 925-0703	6. Rm #:	7. Org. COTS
8. CCR Title: GSFC Baseline Update February 2004						
9. Originator Signature/Date Maryellen Corbett /s/ 2/9/04			10. Class II	11. Type: CCR	12. Need Date: 03/15/2004	
13. CCR Sponsor Signature/Date Pamela Johnson /s/ 02/11/04			14. Category of Change: Update ECS/EMD Baseline Doc		15. Priority: (If "Emergency" fill in Block 27). Routine	
16. Documentation/Drawings Impacted (Review and submit checklist): None			17. Schedule Impact:		18. CI(s) Affected:	
19. Release Affected by this Change: EMD		20. Date due to Customer:		21. Estimated Cost: None - Under 100K		
22. Source Reference: <input type="checkbox"/> NCR (attach) <input type="checkbox"/> Action Item <input type="checkbox"/> Tech Ref. <input type="checkbox"/> GSFC <input type="checkbox"/> Other:						
23. Problem: (use additional Sheets if necessary) Some baseline inconsistencies have been identified. These may involve baseline updates and/or installation/removal of COTS products to resolve identified baseline inconsistencies.						
24. Proposed Solution: (use additional sheets if necessary) Provide baseline red-lines and/or ECOs to resolve identified discrepancies. Attached sheet provides summary of baseline and system administration changes. These changes are also included in the ECO instructions for resolution of identified baseline discrepancies.						
25. Alternate Solution: (use additional sheets if necessary) Accept an inconsistent baseline and installations						
26. Consequences if Change(s) are not approved: (use additional sheets if necessary) Inconsistent baseline and installations						
27. Justification for Emergency (If Block 15 is "Emergency"):						
28. Site(s) Affected: <input type="checkbox"/> EDF <input type="checkbox"/> PVC <input type="checkbox"/> VATC <input type="checkbox"/> EDC <input checked="" type="checkbox"/> GSFC <input type="checkbox"/> LaRC <input type="checkbox"/> NSIDC <input type="checkbox"/> SMC <input type="checkbox"/> AK <input type="checkbox"/> JPL <input type="checkbox"/> EOC <input type="checkbox"/> IDG Test Cell <input type="checkbox"/> Other						
29. Board Comments:			30. Work Assigned To:		31. CCR Closed Date:	
32. SCDV CCB Chair (Sign/Date): Byron Peters /s/ 02/26/04			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
33. EDF CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS			
34. ECS CCB Chair (Sign/Date):			Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS			

ADDITIONAL SHEET

CCR #: 04-0098 **Rev:** — **Originator:** Maryellen Corbett

Telephone: **Office:**

Title of Change: GSFC Baseline Update February 2004

CM Documents:

Discrepancies are from 02/05/2004 run.

GSFC Systems Administration Updates:

1. Anlpassword 3.0 is currently not visible to SGI hosts. A technical directive (Test and release ANLpasswd Engineering Technical Directive 03-006) was released to update installation of Anlpassword 3.0. Update installation with this ETD so that Anlpassword will be visible to all hosts.
2. Remove obsolete versions of Open Client from the following automount installations. Please contact Carol Lindsey for questions or additional information.
 - a. SGI OC 11.1.1 from /tools/sybOCv11.1.1
 - b. SGI OC 12.0.0 from /tools/sybOCv12.0.0 - the correct 12.0.0 version, with EBF is correctly installed in /tools/sybOCv12.0.0EBF
 - c. Sun OC 11.1.1 from /tools/sybOCv11.1.1
 - c. Sun OC 11.1.1 from /tools/sybOCv11.1.1EBF
3. Review installation of PERL 5.6.1 for SGI. Currently only obsolete version of PERL 5.005_3 is visible to SGI hosts. If the intent is to remain out of baseline for this COTS product, an NCR should be generated to reflect this baseline decision by the DAAC.
4. Review installation of TCL/tk 8.3.3. Currently only obsolete version 8.0_PL_4 is visible to SGI hosts. . If the intent is to remain out of baseline for this COTS product, an NCR should be generated to reflect this baseline decision by the DAAC.

CM01AJA00 Revised 10/2/03

ECS/EMD